

HQS COPY

WORK ORDER REQUEST

29 OCTOBER 1958

TO: FP
 ATTN: [REDACTED] STATOTHR
 FROM: RCW

ITEM	PART NUMBER	SERIAL NBR	UNIT	QTY
1.	F2400	24	EA	1 both rec'd
2.	F2400-6	506	EA	1 on 22 Dec '58
///////////////// LAST ITEM ///////////////////				

59-7506

ITEM #1: RETURNED FOR MODIFICATION TO F2400-6

ITEM #2: RETURNED FOR IRAN (Inspection and Repair As Needed)

NOTE: RETURN EACH REGULATOR TAGGED OR OTHER WISE MARKED TO INDICATE THE DATE THE REPAIR IS COMPLETED. EACH REGULATOR MUST BE SUITABLY PACKAGED FOR STORAGE AND THE OUTER CONTAINER MARKED TO INDICATE THE SERIAL NUMBER OF THE REGULATOR; THE DATE REPAIR WAS COMPLETED; AND THE RE-INSPECTION DATE RECOMMENDED IN THE EVENT THAT THE REGULATOR REMAINS IN STORAGE FOR A PROLONGED PERIOD.

HQS COPY

WORK ORDER #: FP-10-30-13

VOUCHER #: 159-5893

CONTRACT #: HF-TM-16

*Posted BB
10-30-58*